



Western Michigan University
ScholarWorks at WMU

Legacy Scout Tickets from Pure Oil Company

8-20-2021

MGRRE_PureOilScoutTickets_Eklund, Louis and Wife_1_21121083500000

MGRRE
Western Michigan University

Follow this and additional works at: <https://scholarworks.wmich.edu/pure>



Part of the Geology Commons

WMU ScholarWorks Citation

MGRRE, "MGRRE_PureOilScoutTickets_Eklund, Louis and Wife_1_21121083500000" (2021). *Legacy Scout Tickets from Pure Oil Company*. 7471.
<https://scholarworks.wmich.edu/pure/7471>

This Document is brought to you for free and open access via ScholarWorks at WMU. It has been accepted for inclusion in Legacy Scout Tickets from Pure Oil Company by an authorized administrator of ScholarWorks at WMU. See the National Digital Catalogue - Science Base Catalogue for more collections submitted by MGRRE.



MGRRE_PureOilScoutTickets_Eklund, Louis and Wife_1_21121083500000

API 21121083500000

Permit Number 8350

Lease Name Eklund, Louis and Wife

Well Number 1

County Muskegon

Township 11N

Range 16W

Section 25

2021 DEQ or Pure co_name Sanders, Robert R.

Pure Number 630

Latitude 43.31367

Longitude -86.15916

THE PURE OIL COMPANY

DATE January 15, 1941No. 630

LOCATION REPORT

COMPLETION RECORD OF WELLS DRILLED BY OTHER OPERATORS

STATE Michigan COUNTY Muskegon TWP. Dalton SEC. 25 TOWN 11^N RANGE 16^W
 WELL No. 1 (SERIAL No. 630) FARM Louis Eklund ACRES

NAME OF STREAM OR WATERS _____ QUADRANGLE SE NE SEOPERATOR Robert C. Lentz, Tr. Map Dalton Township, Muskegon CountyRobert C. Lentz, Tr.Dalton — Muskegon

Feet from North Line of Farm

330 330 " " East " " "330 330 " " South " " "

" " West " " "

990 990 Feet from North Line of Section 1/4 1/4330 330 " " East " " "

" " South " " "

" " West " " "

h 97 Sp 1-9-41

LEGEND

○ LOCATION

⊙ RIG

⊕ DRILLING

⊗ GAS WELL

● OIL WELL

● SMALL OIL WELL

⊙ DRY HOLE

⊙ DRY SHOWING OIL


⊙ DRY SHOWING GAS

⊙ ABANDONED LOCATION

⊙ ABANDONED GAS WELL

⊙ ABANDONED OIL WELL

NOTE: Below make tracing from map, (when no map is obtainable make sketch) showing farm, center of section, this location with measurements and also wells, dry holes, or other locations in the vicinity of this location.



REMARKS:

SIGNED

Superintendent or Foreman.

